


Correction to: Stripping failure of punching pin in GPa-grade steels

Chanhee Won¹ · Seokryul Lee² · Jihoon Seo³ · Sung Hyuk Park⁴ · Jonghun Yoon¹

Published online: 14 October 2017
© Springer-Verlag London Ltd. 2017

Correction to: Int J Adv Manuf Technol
<https://doi.org/10.1007/s00170-017-0791-2>

The original version of this article unfortunately contained a mistake. Figure 9 was originally published with an incorrect image. The correct version of this figure is provided here and the original article was corrected.



The online version of the original article can be found at <https://doi.org/10.1007/s00170-017-0791-2>.

✉ Jonghun Yoon
yooncsmd@gmail.com

- ¹ Department of Mechanical Engineering, Hanyang University, 55 Hanyangdaehak-ro, Sangnok-gu, Ansan-si, Gyeonggi-do 15588, Republic of Korea
- ² Steel Solution Marketing Department, POSCO, Incheon 21985, Republic of Korea
- ³ Erae CS, Jinyoung-eup, Gimhae-si, Gyeongsangnam-do 50870, Republic of Korea
- ⁴ School of Materials Science and Engineering, Kyungpook National University, 80 Daehakro, Bukgu, Daegu 702-701, Republic of Korea