
please take note

The Practical Failure Analysis staff makes every effort to correctly present authors' contributions. Occasionally errors do occur. In Vol. 1(1), p. 60 ("Influence of Plasma Spray Parameters on the Cracking Behavior of Yttria Stabilized Zirconia Coatings," by A. Kucuk, C. G. Dambra, and C. C. Berndt), Fig. 1 was reproduced incorrectly. Part b of Fig. 1 was presented twice (as Part a and as Part b) and Part a was omitted. The correct Fig. 1 is shown below:



categorized according to (a) "low," (b) "medium," and (c) "high" groups depending on their cumulative AE energy released during the tests. Note the differences in scaling.

This is a placeholder for an advertisement.

30 Volume 1(3) June 2001 Practical Failure Analysis