
Index

- 5S 51
- Acceptable quality level (AQL)
 - acceptance sampling
 - MIL standards 171
 - producer risk 158, 159, 160, 162, 163
 - control charts 220
- Acceptance charts 216
- Acceptance sampling 153–7, 160–4
 - attitude sampling 157–8
 - curtailed sampling 164–5, 188–9
 - double sampling 165–8
 - evolution of quality approaches 17
 - MIL standards and tests 170–1
 - producer and consumer risk 158–60
 - sequential probability ratio test (SPRT) 168–70
 - variables sampling plans 173–5
- Adaptive optimization 176
- Adaptive reprogramming 355
- Added value, *see* Value added
- Adversarial situations 332
- Adverse selection 362
- Advertising 361
- Aishin Seiki 63–4
- Alias structure
 - fractional factorial experiments 275–8, 281
 - Taguchi's robust inner–outer arrays design 300
- Alpha testing 356–7
- Amour, Derek 36
- Analysis of variance (ANOVA) 252
 - fractional factorial experiments 282
 - full factorial experiments 266, 267, 273
 - response surface methodology 307, 308
 - Taguchi's robust inner–outer arrays design 298–9
- Analytic Hierarchic Process (AHP) 150–1
- Appellation Controlée 361
- Appraisal costs 37
- Association Française pour Assurance Qualité (AFAQ) 55
- Asymmetric random walk 393
- ATT 58–9, 60
- Attribute control charts 193
- Attribute sampling 157–8
- Audits, quality 331–3
 - ISO-9000 54
 - questionnaire 333–6, 340
- Automation 353
- Auto regressive moving average (ARMA) models 379–80
- Auto regressive (AR) process 379–80
- Availability, process 112
- Average Outgoing Quality (AOQ) 172–3
 - continuous processes 178
 - curve 172
- Average Outgoing Quality Limit (AOQL) 172
- Average run length (ARL) 155
 - and control charts 219–20
 - CUSUM charts 221, 222, 223
 - exponentially weighted moving average charts 373–4
 - Shewart charts 373, 374
 - random walk process 377, 378
 - range process 392, 393

- Average sample number (ASN)
 - curtailed sampling 164–5, 188–9
 - double sampling 166
- Balanced experiments 254, 255
- Balanced Incomplete Block (BIB) Design 313
 - lattice 319
- Bar charts 90
- Bayesian approach
 - decision theory 138–48
 - economic sampling 180–6
 - filtering theory 382, 385–6
- Bayes risk 181
- Bayes theorem (Bayes rule)
 - decision theory 138–9, 141, 145, 146, 147
 - economic sampling 180, 181, 185
 - filtering theory 383, 384
- Beta-binomial model 146–7
- Beta testing 357
- Bi-lateral charts 221
- Binomial distribution 92–5, 116
 - acceptance sampling 158
 - confidence intervals 104–5
 - control charts 211
 - negative 115, 214
 - reputation and quality control, integration of 397
- Block experimental designs 312–14
- Blocking, experimental 254
- Box–Behnken experimental designs 248, 288
- Box–Cox transformations 300
- Boyce, Robert N. 345
- Brainstorming 75
- Buetow, Richard 57
- Business Process Redesign, *see* Reengineering
- Capability index 197–8, 199
 - corrected 197, 199
- Carry-over designs 319
- Cause–effect diagrams, *see* Fishbone diagrams
- c*-charts 193, 213–15
- Central composite design (CCD) 248, 284–8
- Certification, Total Quality Management
 - IBM 58
 - ISO 53, 55–6, 343
 - audits for 334
- Chebyshev's formula 104
- Chi-squared distribution 99, 119
 - confidence intervals 102–3
 - control charts 209
- Common causes of variation 192–3
- Competition 28
- Complexity of systems 29
- Concurrent engineering 7
- Confidence intervals 99–104
 - control charts 205, 209
 - on a proportion 104–5
- Confounding, Latin squares 315
- Conjugate gradient iteration algorithms 305
- Consumer risk
 - acceptance sampling 158–9, 160
 - control charts 220, 221–2
 - filtering theory 389–90
 - variables sampling plans 174, 175
- Continuous processes 176–8
- Continuous sampling procedure (CSP) 172, 177–8
- Contour map analysis 302
- Contracts 337–9
 - franchises 344
 - intra-firm 341–2
 - moral hazard 363
 - Renault and PSA 340–1
 - supply of quality 346, 348, 350
- Control charts 191–5
 - and average run length 219–20
 - constructing 202–16
 - CUSUM 221–5
 - economic 227–8
 - interpreting 225–7
 - practice of 228–32
 - pre-control 217–19
 - process capability 196–202
 - tables 235–7
- Control schemes, design of 393–5
- Cost reducing strategy 325
- Costs of quality (COQ) 323–4
 - economic control charts 227–8
 - inspection 154, 155, 164
 - Bayesian approach 180–1
 - minimization 178–9
 - in manufacturing 10

- Total Quality Management 33, 34, 36–43
 - control position 50
 - see also* Economic theory
- CPM 93
- Crosby, P.B. 46
- Crossed designs 315–16
- CSP-I, *see* Continuous sampling procedure
- Cumulative sum charts, *see* CUSUM charts
- Cumulative sum process (CSP) 375, 376–7
 - filtering theory 382
 - monitoring over time 394–5
 - range process control 391
- Curtailed sampling 164–5, 188–9
- Customer service 329
- CUSUM charts 193, 221–5, 375–6
 - economic 228
- Daniel plots 264
- Data collection systems 354
- Data transformation 320–1
- Decision phases 130–1
- Decision points 129, 130
- Decision rules 130, 131, 135–6
 - expected utility criterion 136–8
 - expected value criterion 131–4
 - Hurwicz criterion 135
 - Laplace criterion 135
 - maximax payoff criterion 134–5
 - minimax cost criterion 134
 - minimax regret criterion 135
- Decision theory
 - Bayes rule and Bayesian decision making 138–48
 - decision rules 131–8
 - decision trees 127–31
 - development 121–2
 - economic sampling 180–1
 - multiple criteria 150–1
 - opportunity loss tables 124–5
 - payoff tables 122–4
 - two actions problem 125–7
- Decision trees 127–30
- Deming, E.W.
 - control charts 228
 - common causes of variation 192–3
 - evolution of quality approaches 17, 18
 - Total Quality Management 43–4
- Deming's wheel 43–4
- De Moivre, Abraham 97
- Dependent variables 239
- Design
 - experimental, *see* Experimental design
 - organizational, Total Quality Management 31
 - quality 7–8
 - robust, *see* Robust design
- Differentiation strategy 325
- Discrete probability distributions 91
- Dodge 17
- Double sampling 165–8
- Drucker, Peter 3
- Dynamic process control, filtering theory 386–8
- Economic control charts 227–8
 - design 393–5
- Economic inspection sampling 178
 - Bayesian approach 180–6
 - inspection costs minimization and prior risk specifications 178–9
 - non-linear objectives 179–80
- Economic theory 358–60
 - information 361–2, 364–6
 - lemon phenomenon 362–3
 - moral hazard 363–4
 - uncertainty 61–2
- Efficiency set 293
- Elementary events 91
- European Foundation for Quality Management 52
- European model, Total Quality Management 52
- Evolution of quality approaches 16–19, 21–2
- EVOP 303, 304
- Excellence, quality as search for 2
- Expected Monetary Value (EMV)
 - criterion 131, 132–3
- Expected Opportunity Loss (EOL)
 - criterion 131, 132–3
- Expected Profit under Perfect Information (EPPI) 132–3
 - economic sampling 182, 185

- Expected quality of service 12, 13
- Expected utility criterion 136–8
- Expected value criterion 131–4, 136
 - economic sampling 185
- Expected Value of Perfect Information (EVPI) 132, 133
- Expected Value of Sample Information (EVSII) 133–4
- Experimental design 239–41, 249–51
 - approach 241–9
 - balanced and orthogonal experiments 254–5
 - carry-over 319
 - data transformations 320–1
 - factorial experiments 255–6
 - Box-Behnken designs 288
 - central composite design 284–8
 - fractional 274–83
 - full 255–74
 - Plackett–Burman designs 283–4
 - Taguchi's orthogonal-outer array designs 288–9
 - factors and levels 251–3
 - Latin squares 314–15
 - lattice 319
 - mixture 319
 - nested or hierarchical 315–17
 - optimal 319
 - randomization, replication and blocking 253–4
 - randomized complete block design 312–14
 - split plot 317–19
- Experimental response 240
- Experimentation 121
- Explanatory variables 239
- Exponentially weighted moving average (EWMA) 370–1
 - average run length 373–4
 - computer aided example 374–5
- External costs 37
- Externalities 359
- Factorial experiments 255–6
 - Box–Behnken designs 288
 - central composite design 284–8
 - fractional 274–83
 - full 356–74
 - Plackett–Burman designs 283–4
 - Taguchi's orthogonal-outer array designs 288–9
- Failure Mode, Effects and Criticality Analysis (FMECA) 81, 82
- Fault-tree analysis 81–2
- F*-distribution 99
 - confidence intervals 103–4
- Federal Express
 - Statistical Quality Index (SQI) 14–15
 - strategic issues 329
- Filtering theory
 - basic concepts 380–6
 - dynamic process, control of 386–8
- Fishbone diagrams 78
 - and FMECA 81
- Fisher, R.A.
 - evolution of quality approaches 17, 121
 - robust design 291
- Five S 51
- Fixed factors 251
- Flexible Manufacturing Systems (FMS) 19
- FMECA 81, 82
- Food and Drug Administration 361
- Ford Motor Company 227
- Forecasting estimates 381, 382
- Fractional factorial experiments 274–83
- France, Total Quality Management certification 55
 - quality circles 50
- Franchises 343–4
- Full factorial experiments 245, 256–74
 - efficiency 248
- Functional costs of quality 40
- Gambler ruin problem 377
- Gambling 136, 137–8
- Game theory 345, 347, 366–7
- Gamma probability distribution 24
- Gauss, Karl Friedrich 97
- GEMBA 51
- Gendre–Otis 57–8
- General Motors (GM) 361, 364
- Geometric distribution
 - acceptance sampling 164
 - exponentially weighted moving average process (EWMA) 370
- Goal programming 150

- Graphical techniques 88–90
- Green zones, pre-control charts 217
- Hazard rate 111–12
- Health care
 - information asymmetry 365–6
 - service quality in 15–16
 - Total Quality Management 62–3
 - measurement of quality 35, 36
- HEIJUNKA 51
- Hewlett-Packard 329
- Hierarchical experiments, *see* Nested experiments
- Histograms 76–7
- Historical evolution of quality
 - approaches 16–19, 21–2
- Human resources 61–2
- Hurwicz criterion 135
- Hypergeometric distribution 157–8
- Hypothesis testing 105–10
- IBM 58
- Individual values charts (*X*-charts), 193, 215–16
- Industrial revolution 16
- Industrial asymmetries 339, 350
 - economic theory 361–2, 364–6
- Information technology (IT)
 - information systems 354
 - reengineering 65, 66
 - software management 354–7
- Inner–outer arrays design 291–301
- Innovation, filtering theory 383
- Inspection 153–4
 - attribute sampling 157
 - in a continuous process 176–8
 - and contracts 339, 346, 349–50
 - costs 154, 155, 164
 - minimization 178–9
 - curtailed sampling 164
 - double sampling 167
 - economic sampling 178–86
 - producer and consumer risk 158, 159, 160
 - rectifying 172–3
 - sequential probability ratio test (SPRT) 170
- Insufficient Reason, Principle of 135
- Integrated learning 398
- Internal costs 37
- International Organization for Standardization (ISO)
 - certification 53, 55–6, 343
 - audits for 334
 - process capability 201
 - Total Quality Management 52, 53–4, 56
- Intra-firm supplier–producer relationships 341–2
- Inventories 48, 50
- Ishikawa, K. 49
- Ishikawa diagrams, *see* Fishbone diagrams
- Japan
 - control of quality 396
 - evolution of quality 18
 - Total Quality Management 46–52
- Japan Institute of Plant Engineers (JIPE) 63
- Juran, J.M.
 - control charts 194
 - evolution of quality approaches 17, 18
 - Total Quality Management 44–5
- Just in Time (JIT)
 - acceptance sampling 158
 - decision rules 133
 - evolution of quality approaches 19
 - strategic issues 327
 - Total Quality Management 46, 48, 49
 - Poka-Yoke 49–50
- Kaizen 50
- Kalman filter 390
- Kalman gain 383, 384, 385, 388
- Kanban 48
- Labels
 - uncertainty over 5–6
 - value added 3
- Lambda plots 300
- Laplace, Pierre Simon
 - normal distribution 97
 - Principle of Insufficient Reason 135
- Laplace criterion 135
- Large numbers, law of
 - experimental replication 254
 - normal distribution 98
 - control charts 204, 205
- Latin rectangles 313

- Latin squares (LS) 314–15
 - carry-over designs 319
- Lattice designs 319
- Learning, integrated 398
- Lemon phenomenon 362–3
- Lexian distributions 92
- Life testing 173–5
- Line charts 90
- Logic diagrams, *see* Fault-tree analysis
- Logistics systems
 - service quality in 14–15
 - strategic alternatives in 328–30
- Losses, valuation of 179
- Lotteries 137–8
- Lot tolerance fraction defective (LTFD)
 - level
 - acceptance sampling 158, 159, 160, 162, 163
 - control charts 220
- Maintainability 113
- Manufacturing
 - quality in 6–10
 - robust processes 10
 - capability index 198
 - technology 350–4
 - Total Quality Management 44
- Marketing channels 342
- Maslow's hierarchy of needs 13
- Mathematical models 121
- Matsushita Electric 49
- Maximax payoff criterion 134–5
- Maximin payoff criterion 134
- Maximum likelihood estimation,
 - filtering theory 386
- Mean residual lifetime 112
- Mean time between failure (MTBF)
 - 112, 113, 114
- Measurement Assurance program (MAP) 201–2
- Measurements of quality
 - assurance 201–2
 - in Total Quality Management 30, 32–43
 - costs 37
- Medical laboratories, Total Quality Management 41–2
- MIL-STD-105 171
- MIL-STD-414 173
- MIL-STD-490 170–1
- Minimax criterion 134
- Minimax regret criterion 135
- Minimin cost criterion, *see* Maximax payoff criterion
- MINITAB
 - central composite design 287
 - control charts 200, 374
 - full factorial experiments 264, 269, 273
 - Plackett–Burman designs 284
- Mixture experiments 319
- 'Moment of Truth' 14
- Monitoring over time 394–5
- Moral hazard 332, 339, 363–4
- Motorola 57
- Moving average (MA) 370, 371, 372
 - auto regressive (ARMA) 379–80
 - computer aided example 374
 - exponentially weighted (EWMA) 370–1
 - average run length 373–4
 - computer aided example 374–5
- MUDA/MURA/MURI 51–2
- Multi-criteria decision making 150–1
- Multi-stage decision trees 130
- Nash equilibrium 366
- Negative binomial distribution (NBD)
 - 115
 - control charts 214
- Nested experiments 315–17
 - factorial 317
- New product development, strategic
 - alternatives in 331
- Newton iteration algorithms 302, 305
- Neyman–Pearson theory 337
- Nissan 35–6
- Non-detection 37
- Non-zero sum game 366
- Normal distribution 95, 97–9, 117
 - acceptance sampling 161–2
 - Bayes theorem 145–6
 - confidence intervals 101, 103, 105
 - control charts 198, 204, 205, 206
 - economic inspection sampling 179–80
 - filtering theory 390–1
- Normal plots
 - fractional factorial experiments 282
 - full factorial experiments 264, 265

- Normal probability plots 264
- No Touch Ratio (NTR), Nissan 35
- np*-charts 193, 211
- Numerically Controlled Machines (NCM) 176
- Off-line quality control 240
- Olson, James E. 59
- One-at-the-time experiments 247–8
- One-sided CUSUM charts 223–4
- On-target objective 294
- Operating characteristic (OC) curves
 - acceptance sampling 163
 - control charts 204
 - hypothesis testing 106–7
- Opportunity loss tables 124–5, 182
- Optimal cost of quality 40
- Optimal experimental designs 319
- Optimist criterion, *see* Maximax payoff criterion
- Organizational design 31
- Orthogonal experiments 254–5
- Othogonal Latin squares 314
- Orthogonal-outer array designs 288–9
- Otis 35
- Over-parameterized models 251
- Over-simplification of quality issues 332
- Pareto, Wilfred 78–9
- Pareto charts 78–80
 - and FMECA 81
 - multi-criteria decision-making 150
- Partially balanced incomplete block (PBIB) design 313
- Payoff tables 122–4
- p*-charts 193, 210–11
- PDCA cycle 63
- Pearson, Karl 121
- Perceived quality of service 12–13
- Perrier 361
- Perron–Frobenius eigenvector 151
- PERT 83
- Peugeot 340–1
- Phillips 60
- Pie charts 90
- Plackett–Burman (PB) designs 283–4
- Planning of experiments 121
- Poisson distribution 95–7
 - acceptance sampling 160
 - control charts 211, 213–14, 229–30
 - and negative binomial distribution 115
- Poka-Yoke 49–50
- Portfolio approach 292–3
- Potential, process 197
- Pre-control 217–19
- Pre-posterior analysis 143–4
- Prevention of defects
 - inspection for 153
 - rectifying 172
 - Total Quality Management 30–1
 - costs 37, 39–40
- Price of non conformity (PONC), Otis 35
- Probability density functions 91
- Probability distributions 91–2
 - beta 146–7
 - binomial, *see* Binomial distribution
 - chi-squared 99, 102–3, 119, 209
 - F* 99, 103–4
 - gamma 214
 - geometric 164, 370
 - hypergeometric 157–8
 - negative binomial 24, 115
 - normal, *see* Normal distribution
 - Poisson, *see* Poisson distribution
 - sample size 204
 - Student's *t* 99, 102, 118, 206
 - Weibull 113–14
- Process availability 112
- Process capability, control charts 194, 196–202
 - pre-control 217
- Producer risk
 - acceptance sampling 158–9, 160, 164
 - control charts 220, 221–2
 - filtering theory 388, 389–90
 - variables sampling plans 174
- Producer–supplier relationships 323, 337–8
 - contracts, *see* Contracts
 - franchises 343–4
 - intra-firm 341–2
 - marketing channels 342
 - protocols in 342–3
 - quality supply 346–50
 - virtual supplier integration 345
- Producibility 7
- Production lines 16
- Programming 356–7

- Project management 82–4
- Proportions, confidence intervals on
 - 104–5
- PSA (Peugeot) 340–1
- Pull scheduling 48

- Q-Q plots 264
- Quadratic loss function 179
- Qualitative factors 251
- Quality
 - audits, *see* Audits, quality
 - circles of 324
 - concept of 1–4
 - costs, *see* Costs of quality
 - definition, and measurement 35–6
 - design 7–8
 - economic theory 358–66
 - historical evolution of approaches to
 - 16–19, 21–2
 - in manufacturing 6–10
 - measurement, *see* Measurements of quality
 - and services 10–16
 - spillover effects 395–6
 - spiral 45
 - strategic issues, *see* Strategic issues
 - supply 346–50
 - terms 24–5
 - tools of, *see* Statistical tools
 - trauma 8
 - and uncertainty 4–6
- Quality assurance
 - health care 62, 365–6
 - Renault and PSA 340–1
- Quality circles 50–1
- Quality control
 - off-line 240
 - and reputation, integration of
 - 396–8
- Quality improvement (QI)
 - approaches to 43–53
 - control charts 194–5
 - health care 62–3
- Quantas Airways 15
- Quantitative factors 251
- Questionnaires, audit 333–6, 340

- Randomization of experiments 253–4
- Randomized complete block design
 - 312–14

- Randomness
 - factors 252
 - Latin squares 314
 - manufacturing 8
 - split plots 318
 - tests for 225
- Random variables 91
- Random walk process 377–9
 - range process control 392–3
- Range charts, *see* R-charts
- Range process control 391–3
- R-charts 193, 208–9
 - and \bar{x} -bar charts 205, 208
- Red zones, pre-control charts 217
- Reengineering 64–6
- Reliability
 - function 111–14
 - testing 153
- Renault 340–1
- Replication, experimental 254
- Reproducible processes 145–6
- Reproducibility property, normal
 - distribution 98
- Reprogramming 356
 - adaptive 355
- Reputation, integration of quality
 - control and 396–8
- Response model approach 301
- Response surface methodology (RSM)
 - 301–4
 - application of 306–9
 - and optimization 304–6
 - rotatable experimental design 285
 - Taguchi's robust inner–outer arrays
 - design 301
- Risks
 - consumer, *see* Consumer risk
 - curtailed sampling 164–5
 - prior specifications 178–9
 - producer, *see* Producer risk
 - specification 154–5
 - and uncertainty 5
 - management 136–7
- Robust design 240, 289–91
 - response surface methodology 301–9
 - strategic issues 326, 328
 - Taguchi's robust inner–outer arrays
 - design 291–301
- Robustness
 - in manufacturing 10

- capability index 198
 - in programming 356
- Rotatable experimental design 285
- Run tests 225, 226–7
- Sample size
 - control charts 204, 224
 - decision theory 148
- Sample space 91
- Sampling
 - acceptance, *see* Acceptance sampling
 - attribute 157–8
 - and contracts 350
 - control charts 204, 218
 - curtailed 164–5, 188–9
 - double 165–8
 - economic inspection 178–86
 - monitoring over time 394
 - multiple considerations 154, 155
 - rectifying inspection 172
 - variables plans 173–5
- Savage's criterion 135
- Scatter plots 76, 77
- s*-charts 193, 209–10
 - and *x*-bar charts 205, 208
- s*²-charts 193, 209–10
- Screening experiments 256
- Sequential probability ratio test (SPRT) 168–70, 375
- Services
 - experimental design in 278–80
 - quality in 10–16
 - Total Quality Management 61–2
 - costs of quality 42–3
- SERVQUAL 27–89
- Shewart, W.A.
 - control charts 191
 - evolution of quality approaches 17
- Shewart charts 193
 - average run length 373, 374
 - and CUSUM charts, comparisons 222, 223
- Shop Floor, Shigeo Shingo's 49–50
- Signal to Noise (*S/N*) ratio 290, 292, 294–5, 296–7
- Simon, Herbert 136
- Sloet, J.F.A. 2–3
- Smoothing estimates 381, 382
- Software management 354–7
- Sony Alsace
 - acceptance sampling 159
 - cost of quality 50
- Special causes of variation 192
- Spillover effects of quality 395–6
- Spiral of quality 45
- Split plot experimental designs 317–19
- Split-split-plot experimental designs 318
- Standard Associations 17
- Starr, Martin K. 67
- Statistical data analysis 121
- Statistical Quality Control (SQC) 31
- Statistical Quality Index (SQI), Federal Express 14–15
- Statistical tools 73–5, 91–2
 - brainstorming 75
 - confidence intervals 99–105
 - decision theory, *see* Decision theory
 - distributions, *see* Probability distributions
 - evolution of quality approaches 17
 - fault-tree analysis 81–2
 - fishbone diagrams 78
 - FMECA 81, 82
 - graphical techniques 88–90
 - histograms 76–7
 - hypothesis testing 105–10
 - in manufacturing 8
 - Pareto charts 78–80
 - project management 82–4
 - reliability function 111–14
 - risk specification 154–5
 - scatter plots 76, 77
 - tally sheets 75, 76
 - value analysis 80
- Steepest descent algorithms 302, 305
- Step-loss function 179
- Straight Through Ratio (STR), Nissan 35
- Strategic issues 323–8
 - logistics transportation systems 328–30
 - new product development 331
 - and technology 350–4
- Strict inspection 159
- Student's *t* distribution 99, 118
 - confidence intervals 102
 - control charts 206
- Sufficient statistics 146
- Supplier–producer relationships, *see* Producer–supplier relationships

- Suppliers Quality Assurance
 - Programme, Renault and PSA 340–1
- Switzerland, Total Quality Management 57–8
- Symmetric random walk 377, 393
- Taguchi, G., experiment design 245
 - data transformation 320
 - orthogonal-outer array designs 288–9
 - robust inner-outer arrays design 291–301
 - Signal to Noise ratio 290, 292, 294–5, 296–7
 - split plots 317, 318
- Tally sheets 75, 76
 - Pareto charts 80
- Taylor, Frederick 16
- t*-distribution, *see* Student's *t*-distribution
- Technology
 - feedback loop 353–4
 - and strategic quality management 350–4
 - see also* Information technology (IT)
- Temporal processes
 - ARMA models 379–80
 - CSP-processes 376–7
 - CUSUM charts 375–6
 - design of control schemes and economic charts 393–5
 - filtering theory 380–8
 - integrated learning 398
 - integration of quality control and reputation 396–8
 - MA and EWMA 370–5
 - random walk process 377–9
 - range process, control of 391–3
 - statistical control 388–91
- Tolerant inspection 159
- Tool wear 352
- Total Production System (TPS), Toyota 52
- Total Productive Maintenance (TPM) 63–4
- Total Quality Control (TQC)
 - certification 53
 - evolution of quality approaches 18
 - in manufacturing 9
- Total Quality Management (TQM) 27–32
 - approaches to 43–53
 - certification and ISO 9000/9004 53–7
 - evolution of quality approaches 18
 - examples and applications 57–63
 - experimental and robust design 240, 241
 - implementation 66–7
 - inspection, preventive 153
 - in manufacturing 8
 - measurements and control in 32–43
 - producer–supplier relationships 337, 338
 - intra-firm 341
 - moral hazard 364
 - and reengineering 64–6
 - tools of, *see* Statistical tools
 - Total Productive Maintenance 63–4
- Toyota
 - Poka-Yoke 49
 - Total Production System 52
- Training 64
- Transportation systems, strategic
 - alternatives in 328–30
- TRW 59–60
- Two actions problem 125–7
- Two-stage decision trees 130
- Type I errors 106
- Type II errors 106
- u*-charts 103, 215
- Uncertainty
 - decision making under, *see* Decision theory
 - economic theory 361–2
 - formulation of problems under 122–5
 - and quality 4–6
 - statistical tools 8
- United Parcel Service 328
- United States of America
 - evolution of quality approaches 17–18
 - quality circles 50
- Utility function 138
- Utility theory 135, 136, 137–8
- Value added
 - quality as 3
 - in manufacturing 9
 - and uncertainty 4, 5

- Total Quality Management 30
- Value analysis 80
- Variable control charts 193
- Variables
 - dependent 239
 - explanatory 239
- Variables sampling plans 173
 - life testing 173–5
- Varian 323
- Variance component models 252
- Vector moving average model 379
- Virtual supplier integration 345
- V-mask technique 225

- Wald, A., sequential probability ratio test 168–70

- Wal-Mart 329
- Warranties 337
- Weibull distribution 113–14
- Wiener process 392

- \bar{x} -bar charts 193, 205–8
- \bar{X} -charts (individual values charts) 193, 215–16

- Yellow zones, pre-control charts 217
- Youden squares 315

- Zero defects
 - decision rules 133
 - Total Quality Management 30
 - Just in Time 48
 - Poka-Yoke 49